Real-Time SPC™ 7.8

Table of Contents

1. Problems Resolved in Real-Time SPC 7.8

The following issues are resolved in Real-Time SPC 7.8.

- Cannot rename components to alter capitalization of characters. (231395)
- Components: Top Bar Options are still enabled after moving a component. (248146)
- Global Descriptor being checked mistakenly in Sampling Plan. (249823)
- Automated Component Setup not honoring default descriptor values when unspecified. (251654)